#### **Miami Office**

80 SW 8th Street, Suite #2000 Miami, FL 33130

Tel (800) 403-9011 Fax (800) 403-7511 www.reservestudy.com



**Regional Offices** 

Arizona California Colorado Florida Hawaii Nevada Washington

April 13, 2015 Association # 28828-0

Silver Point Condominiums c/o Mr. Johann Swart Board of Directors 74 Silverpoint Condominiums Acacia Road, Freeport, Bahamas

Subject: Reserve Study Proposal

Dear Johann,

Thank you for requesting a Reserve Study proposal from Association Reserves. It would be our privilege to serve as your Reserves planning partner! We recognize that you have a choice of Reserve Study providers and want to make sure you understand the many benefits of working with our company:

- Your Reserve Study will be prepared in accordance with <u>National Reserve Study Standards™</u> by a credentialed Reserve Specialist™
- Your Report (and other files) will be posted online for easy, anytime access
- Your free Video Explanation of Results will help you communicate with Boardmembers and Homeowners
- Your free Funding Analysis Software will allow you to compare various "what-if" scenarios

All of our complete, accurate, and user-friendly 30-yr Reserve Studies contain three key results:

- 1. Component List detailing the scope and schedule of all Reserve Projects
- 2. Calculation of current Reserve Fund Strength (% Funded)
- 3. <u>Customized Funding Plan</u> going forward that allows for timely repairs & replacements, with an emphasis on avoiding special assessments

When you're ready for the next step, simply sign and return the Agreement along with a 50% deposit on the total fee for the Study. Our office will then contact you regarding the next steps in the process, such as scheduling the site inspection, obtaining required background information, etc. Please don't hesitate to contact us if you have any questions or concerns, or would like any additional information. We hope to hear from you soon!

Sincerely,

Will Simons, RS

President

Florida/Southeast Regional Office

### **Introduction to Reserve Studies**

### What's a Reserve Study?

A Reserve Study is best described as a document used by community associations (or any other type of common interest real estate development) to help plan financially for major repair, replacement, or restoration projects over a long period of time. Our studies cover a thirty year timeframe, beginning with the current or upcoming fiscal year. There are two main sections in a Reserve Study: the **Physical Analysis** and the **Financial Analysis**.

### Are Reserve Studies really that important?

Absolutely. It's fairly easy to plan and prepare for recurring costs like management fees, insurance premiums, landscaping contracts, and utilities, but what about the projects and expenses that DON'T happen every year? That's our specialty...identifying and forecasting those projects that are *certain* to occur, but are often overlooked or underestimated. There's no question that setting aside Reserve funds over a long period of time is the simplest, most cost-effective, and most responsible way to plan for major projects.



The work <u>will</u> need to be done; it's up to the association to plan accordingly. Without adequate Reserves, associations will have to make a tough decision: will you take out costly loans, push for recurring special assessments, or worst, accept a drop in home values due to deteriorating conditions and deferred maintenance? A current, reliable Reserve Study is the first step toward long-term financial strength for every association. Without one, association homeowners will be misinformed, underprepared, and left exposed to serious financial consequences. A current, reliable Reserve Study is a hallmark of well-managed associations, and an important part of a homeowner board's fiduciary duty to act in the best interest of their association members.





# What components are included in a Reserve Study?

The National Reserve Study Standards specify the following definition of a Reserve Component:

- · Must be the association's responsibility.
- · Must have a limited Useful Life (UL)
- · Must have a predictable Remaining Useful Life (RUL)
- · Must be above a certain "threshold cost"

We typically recommend funding for projects such as: roof replacement, painting/waterproofing, pavement sealing and resurfacing, elevator modernization, balcony and deck sealing and restoration, major mechanical systems (HVAC, fire alarm, hot water, etc.), major pool and spa expenses, interior/amenity area remodeling, and many more. The bottom line is that every property is different, and will require a thorough inspection to determine what belongs in your study.

State requirements vary on what types of projects should be addressed through Reserves (and therefore included in a Reserve Study). Our studies will always meet and usually exceed these requirements, ensuring that our clients are acting in accordance with legal requirements and sound fiduciary responsibility.







# **Scope of Work**

Our Reserve Studies are prepared in accordance with National Reserve Study Standards, established in 1998 by the Community Associations Institute. Per these standards, a Reserve Study engagement generally consists of the following:

### 1. Component Inventory & Condition Assessment

The component inventory is "the task of selecting and quantifying Reserve Components. This task can be accomplished through on- site visual observations, review of association design and organizational documents, a review of established association precedents, and discussion with appropriate association representative(s) of the association or cooperative." The condition assessment is "the task of evaluating the current condition of the component based on observed or reported characteristics." As part of our inspection, we review any available building documents including site plans, building plans, fire alarm inspection records, equipment schedules and any other data that may be informative regarding component details, project history or expectations for upcoming work. We then photograph, measure and inspect all areas or components to be included. A Reserve Study site inspection is visual in nature and does not incorporate any destructive or other testing. The inspection is not intended to identify code or construction defects, nor is it intended to be the foundation for anything other than budgeting and planning purposes.

**NOTE:** For Update, With Site Visit (Level 2) Reserve Studies, the component inventory is for verification purposes only, using previously-established component quantities from a prior Reserve Study. However, the condition assessment is re- established based on current conditions. For Update, No Site Visit (Level 3) Reserve Studies, there is no physical inspection of the property. We review the component inventory and condition assessments from the most recent Level 1 or Level 2 study, then proceed with the Life and Valuation Estimates and Financial Analysis.



#### 2. Life & Valuation Estimates

This process is usually much more time consuming than the actual site inspection, and represents the bulk of the overall Reserve Study process. Our Reserve Specialist® begins by organizing and interpreting the raw data he or she gathered during the site inspection, reviewing all measurements, notes and photographs for key details and insights. Next, we establish the component list structure, and determine the life and cost estimates for each Reserve component. Our standard procedure is to use any historical information provided to us by the client (such as when certain projects were done, and what they cost), and to review any bids or estimates for upcoming work. We review our findings with your current vendors for their insights, and also check their input against information we've gathered working with other comparable properties in your area. We constantly consult our own internal databases, comprised of data collected from over 30,000 Reserve Studies. As a supplement, we also make use of professional construction estimating software programs, guidebooks, publications and manufacturer's publications to supplement our knowledge base. The end result is a complete, thorough set of estimates that are accurate, current, property-specific, and generated by a qualified, independent third party.

#### 3. Financial Analysis, Report Preparation & Delivery

Once the component list is established and we've reviewed your current annual budget and Reserve fund balance(s), we will make a determination of relative current Reserve fund strength and created a recommended funding plan covering the next 30 fiscal years, including a schedule of projected annual income and expenses.





# Why should we choose Association Reserves?

Association Reserves was established in 1986 as a professional engineering consulting firm serving community associations throughout the United States and abroad. To date, our firm has completed over **30,000** Reserve Studies for properties of all types, including condominium and homeowners associations, community development districts, timeshare and resort properties, commercial facilities, worship facilities, and more. Over the years, our firm has been instrumental in defining and advocating the National Reserve Study Standards endorsed by the Community Associations Institute (CAI).

Each Reserve Study we provide is conducted with special consideration for the unique characteristics of the client property, especially age, regional weather patterns, local pricing factors, and input from the Board of Directors. Our time-tested approach involves thorough research of all key factors, especially project history, projected useful life and cost data, and aesthetic standards in the local area. Our staff members earn and maintain the Reserve Specialist® credential administered by the Community Associations Institute (CAI), the international authority on all aspects of community association living.

We don't take a one-size-fits-all approach to our work, because we know that every association is different, and we take the time and care to ensure our results will help you to make wise decisions regarding the long-term care of your physical and financial assets. From our first phone call to final delivery of your study, we hold ourselves to the highest standards of professionalism. We pride ourselves on delivering a first-rate product, because we know you're putting your trust in our hands.

We're proud to announce that in 2013 we were selected as a Platinum-level Reader's Choice Award winner in the first ever competition put on by the Florida Community Association Journal. We attribute this achievement to a combination of hard work, attention to detail and an unwavering commitment to serving our clients.







# **Qualifications and Key Staff Members**

All of our project staff members have college degrees and many come from construction, engineering, architecture and related backgrounds. All project management staff members are trained specifically in the field of preparing Reserve Studies. As of 2014, over 20 staff members have earned the prestigious Reserve Specialist credential, more than any other firm in the country.



Robert M. Nordlund, PE, RS is the founder, owner and CEO of Association Reserves. Robert is a Professional Engineer, Reserve Specialist, and former board president of his own homeowners association. In addition, he is a past Chairman of CAI's Reserve Professionals Committee, past Chairman of the Association of Professional Reserve Analysts, past President of CAI's Greater Los Angeles Chapter, and a frequent speaker in industry-sponsored seminars and presentations throughout the United States. He obtained his Bachelor's degree from the University of Washington in Mechanical Engineering, and is a member of the prestigious engineering honors society Tau Beta Pi.



Will Simons, RS is the President of our Florida regional offices. Will has completed over 800 Reserve Studies for property types including residential developments, schools, historic buildings, commercial developments, country clubs, worship facilities, marinas and more. Will has earned the Reserve Specialist designation (#190) and is also a frequent author and speaker in the industry. He is a licensed Continuing Education Provider (#0005433) for Florida Community Association Managers, having designed and taught coursework related to Reserve funds and Reserve Studies. He currently serves as the Treasurer of his own homeowners association in South Florida, serving a community of over 600 homes and helping to oversee an annual budget of over \$1 million. Will earned a Bachelor's degree in Business Administration from the University of Southern California.




Aldo Gonzalez, PE is the Director of Operations for our Florida regional offices. Aldo holds a Bachelor's of Science Degree in Civil Engineering from Florida International University and is a Registered Licensed Engineer (#49450) in the State of Florida. Aldo's career has spanned over 30 years of civil engineering and project management roles. For over 15 years, he directed his own engineering consulting firm, providing services including: general engineering consulting, real estate asset inspection, planning and feasibility studies, engineering reports and design calculations, drainage and paving design, water, sewer and flood control system design and more to a wide variety of clients throughout Florida. Aldo has also served as Board Member for the Palm Isle at Doral Community Development District in Doral, Florida.






# What can I expect to see in my Reserve Study?

Simple, concise summary of recommendations, with a clear, organized listing of Reserve components.



105   Balcony Decks - Resurface   28   27   3246,500	Table 1	1. Executive Summary				9990
Sample Condo - Exercior Grange   105   Balcony Decks - Record   5   4   599,000     105   Balcony Decks - Resultace   28   27   3246,500     105   Balcony Decks - Resultace   24   23   37,600     106   Sale - S		Component	Life	Useful	Average	Futu Avera Co
105 Balcony Decks - Resurface   28   27   3346,500	1		97			
201   Asphalt - Resurface   24   23   77.000   202   Asphalt - Resultinguist   4   3   5693   324   Exterior Lighting - Replace   29   19   333,413   325   Exterior Lighting - Replace   29   19   333,413   326   Exterior Lighting - Replace   20   19   333,413   327   Main Entirance Doors - Replace   25   24   317,500   328   Exterior Turnture - Replace   25   24   317,500   328   Exterior Turnture - Replace   3   7   150,000   328   Exterior Turnture - Replace   3   7   150,000   329   Exterior Replace   3   7   150,000   320   Exterior Replace   3   7   157,000   320   Post - Resurface   5   4   33,125   320   Post - Resurface   5   5   20   20   320   Post - Resulting   7   30   30   320   Exterior Flantier - Waterproof   15   14   255,000   320   Exterior Flantier - Waterproof   15   14   255,000   320   Exterior Flantier - Replace   25   24   20,613   320   Exterior Flantier - Replace   25   26   20,613   320   Exterior Flantier - Replace   27   211,425   320   Exterior Flantier - Replace   3   7   311,425   320   Exterior Flantier - Replace   3   7   311,425   320   Office Furnishing   7   310,000   321   Post   7   310,000   322   Exterior Flantier - Replace   3   31,500   323   Post   7   310,000   324   Exterior Flantice - Replace   3   31,500   325   Post   7   310,000   326   Exterior Flantice - Replace   3   31,500   327   Exterior Flantice - Replace   3   31,500   328   Exterior Flantice - Replace   3   31,500   329   Collegio Flantice - Replace   3   31,500   320   Office Furnishing   7   310,000   320   Exterior Flantice - Replace   3   31,500   320   Exterior	104	Balcony Decks - Re-coat	5	4	\$99,000	\$111,42
202	105	Balcony Decks - Resurface	28	27	\$346,500	\$769,67
224 Exterior Lighting - Replace   20   19   533,613   226 Garappt Lighting - Replace   20   29   54,200   270 Main Estimates Doors - Replace   15   14   53,000   271 Main Estimates Doors - Replace   15   14   53,000   272 Main Estimates - Replace   15   14   53,000   273 Exterior Furniture - Replace   18   7   150,000   274 Exterior Furniture - Replace   18   7   150,000   275 Exterior Replace   19   170,000   275 Exterior Replace   19   170,000   270 Pool - Resurrace   19   170,000   270 Forth Common Modified Root - Replace   19   170,000   270 Forth Common Modified Root - Replace   19   170,000   270 Exterior Planter - Waterproof   15   14   125,000   270 Exterior Planter - Waterproof   19   170,000   270 Exterior Planter - Waterproof   170,000   270 Exterior Planter - Waterproof   1			24		\$7,600	\$14,99
226 Garage Lights - Replace   20   24   200						\$75
Total   Main Entrance   15		Exterior Lighting - Replace				\$58,94
202   Garage Carles - Replace   25   24   517,500	326	Garage Lights - Replace	30	29	\$4,200	\$9,89
993 Exterior Furniture - Replace 8 7 \$100,000   1111 Gargue Interior - Repaint 1 4 13 519,125   1115 Shucco - Repaint 1 4 13 519,125   1115 Shucco - Repaint 1 7 9 \$7,225   1115 Shucco - Repaint 1 7 9 \$7,225   1115 Shucco - Repaint 1 7 9 \$7,225   1116 Shucco - Repaint 1 7 9 \$7,225   1120 Polis - Resurface 1 0 9 \$23,000   1202 Spa - Resurface 5 4 \$3,000   1203 Spa - Resurface 5 5 4 \$3,000   1203 Spa - Resurface 5 5 4 \$3,000   1204 Spa - Resurface 5 5 4 \$3,000   1205 Spa - Resurface 7 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	701	Main Entrance Doors - Replace	15	14	\$3,900	\$5,89
1111   1115   115   115   11	702	Garage Gates - Replace	25	24	\$17,500	\$35,57
1115 Shacoo - Repaint 1118 Parking Spaces - Restripe 7	903	Exterior Furniture - Replace	8	7	\$160,000	\$196,78
1115 Stacco - Repaint 10 9 \$7.255 1115 Parking Spaces - Restripe 7 6 \$17.200 1120 Relique - Record 5 4 \$1.710 1121 Relique - Record 5 4 \$1.710 1122 Spa - Resurface 5 4 \$1.710 1123 Spa - Resurface 5 4 \$1.710 1124 Spa - Resurface 5 4 \$1.000 1125 Spa - Resurface 5 4 \$1.000 1126 Spa - Resurface 5 4 \$1.000 1127 Tech-Court Modified Relot - Replace 20 19 \$88.200 127 Tech-Court Modified Relot - Replace 10 9 \$153.400 1280 Building Envelope - SealWaterproof 10 9 \$400,000  Sample Condo - Interior Areas 25 £15 Spa - Replace 25 24 \$20,613 261 Corridor Corpart - Replace 25 24 \$20,613 261 Corridor Corpart - Replace 25 24 \$20,613 261 Corridor Corpart - Replace 12 \$11,500,63 261 Corridor Corpart - Replace 12 \$11,500,63 262 Corpare - Replace 12 \$11,510,603 263 Corpare - Replace 12 \$11,510,603 264 Corpare - Replace 12 \$11,510,603 264 Corpare - Replace 10 9 \$10,000 265 Corpare - Remodel 10 9 \$10,000 275 Corpare -	1111	Garage Interior - Repaint		13	\$19,125	\$28,08
1130   Nelipad - Recoat   5   4   31,125   1202   Pool - Resurrice   10   9   228,000   1203   5ga - Resurrice   5   4   54,000   1203   5ga - Resurrice   5   4   54,000   1203   5ga - Resurrice   5   4   54,000   1203   701   701   701   701   701   701   1204   701   701   701   701   701   701   1205   Building Pervice - Seal/Varraproof   5   14   255,000   1206   201   701   701   701   701   701   701   1207   801   701   701   701   701   701   701   1208   Building Pervice - Seal/Varraproof   5   14   255,000   1208   Ext   5ga - 701   701   701   701   701   701   1209   Building Pervice - Seal/Varraproof   5   24   200   701   1209   201   701   701   701   701   701   701   1209   701   701   701   701   701   701   701   701   1201   701   701   701   701   701   701   701   701   701   1201   701	1115	Stucco - Repaint			\$7,925	\$10,34
1202   Pool - Resurface   10   9   \$23,000	1118	Parking Spaces - Restripe	7	6	\$17,200	\$20,53
1203 Sgs - Resurface   5   4   8,000	1130	Helipad - Recoat	5		\$3,125	\$3,51
1304 Deck Underfuryment - Replace	1202	Pool - Resurface	10	9	\$28,000	\$36,53
1307 Torch-Oown Modified Roof - Replace   20   19   5138,450   1705 Exterior Flatters - Waterpoord   15   14   2365,000   1980 Building Envirolog - Sast/Vaterpoord   10   9   460,000   1800 Building Envirolog - Sast/Vaterpoord   10   9   460,000   1800 Building Envirolog - Sast/Vaterpoord   10   9   460,000   1800 Building Envirolog - Sast/Vaterpoord   25   24   328,613   100 Building Envirolog - 1800 Building - 1800 Building Envirolog - 1800 Building - 1800	1203	Spa - Resurface	5	4	\$8,000	\$9,00
Sample Condo - Interior Areas	1304	Deck Underlayment - Replace	20	19	\$88,200	\$154,65
Sample Condo - Interior Areas	1307	Torch-Down Modified Roof - Replace	20	19	\$138,450	\$242,77
Sample Condo - Interior Areas	1705	Exterior Planters - Waterproof	15	14	\$265,000	\$400,83
228 Ext Signis - Registee   30   29   \$32,000   403 Malliboses - Registee   25   24   \$126,013   601 Corridor Carpet - Registee   10   9   \$116,000   602 Cym Equity, Accessories - Registee   17   11   110,000   603 Cym Equity, Accessories - Registee   17   11   110,000   604 Carbon-Harman - Registee   17   11   110,000   605 Common - Area Bathroomer - Registee   12   11   110,000   607 Common - Area Bathroomer - Registee   12   11   110,000   608 Common - Area Bathroomer - Registee   12   11   110,000   609 Common - Area Bathroomer - Registee   10   9   110,000   609 Common - Area Bathroomer - Registee   10   9   150,000   600 Common - Area Bathroomer - Registee   10   9   150,000   600 Common - Area Bathroomer - Registee   10   10   100,000   600 Common - Common - Registee   10   10   100,000   600 Common - Common - Registee   10   9   170,000   600 Common - Common - Registee   10   9   170,000   600 Common - Comm	1980	Building Envelope - Seal/Waterproof	10	9	\$460,000	\$600,19
403 Mailbours - Replace 25 24 20,613 401 Corridor Carpart - Replace 10 9 3116,000 100 20 20 20 20 20 20 20 20 20 20 20 20 2		Sample Condo - Interior Areas		_		
001   Corridor Carpet - Replace   0   9   \$116,000	326	Exit Signs - Replace	30	29	\$32,000	\$75,41
601 Corridor Carpet - Replace   10   9   \$116,000   102 Cym Equip, Accessories - Replace   8   7   \$111,425   103 Lobby Furnifurel Arwent - Replace   12   11   \$150,665   104 Louise - Replace   12   11   \$150,665   105 Lobby Furnifurel Arwent - Replace   12   11   \$150,665   105 Lobby Furnifurel Arwent - Replace   12   11   \$12,000   105 Common Area Bathrooms-Remodel   12   11   \$12,000   106 Common Area Bathrooms-Remodel   12   11   \$12,000   107 Common Area Bathrooms-Remodel   10   9   \$15,000   108 Lobby Furnifurel   10   9   \$15,000   109 Lobby Furnifurel   10   10   \$10,000   1110 Saliveil Interiors - Repaint   15   14   \$43,000   1100 Elevator Codes - Remodel   10   9   \$70,000   100 Elevator Codes - Remodel   10   9   \$70,000   105 Elevator Codes - Remodel   20   19   \$9,000   107 Sample Condo - Mochanical Systems   20   20   \$10,000   108 AC Condoming Units - Replace   20   19   \$9,000   109 AC Condoming Units - Replace   20   19   \$9,000   109 Peckaped AC Units - Replace   20   19   \$15,000   109 Peckaped AC Units - Replace   20   19   \$15,000   100 Peckaped AC Units - Replace   20   19   \$15,000   100 Peckaped AC Units - Replace   20   19   \$15,000   100 Peckaped AC Units - Replace   20   19   \$15,000   100 Peckaped AC Units - Replace   20   19   \$15,000   100 Peckaped AC Units - Replace   20   19   \$15,000   100 Peckaped AC Units - Replace   20   19   \$15,000   100 Peckaped AC Units - Replace   20   19   \$15,000   100 Peckaped AC Units - Replace   20   19   \$15,000   100 Peckaped AC Units - Replace   20   19   \$15,000   100 Peckaped AC Units - Replace   20   19   \$15,000   100 Peckaped AC Units - Replace   20   19   \$15,000   100 Peckaped AC Units - Replace   20   19   \$15,000   100 Peckaped AC Units - Replace   20   19   \$15,000   100 Peckaped AC Units - Replace   20   19   \$15,000   100 Peckaped AC Units - Replace   20   19   \$15,000   100 Peckaped AC Units - Replace   20   19   \$15,000   100 Peckaped AC Units - Replace   20   19   \$15,000   100 Peckaped AC Units - Replace   20   19   \$15,000   1	403		25	24	\$26,613	\$54.09
2001	601		10	9	\$116,000	\$151.35
993   Octoby Furnitural Knews - Replace   12   11   \$150,663	902	Gym Equip. Accessories - Replace		7	\$111.425	\$137.03
994 Kitchenettes - Rafurbish 10 9 \$10,000 910 240 Longer - Remodel 12 11 \$125,000 910 240 Longer - Remodel 12 11 \$125,000 910 910 Common Area Batheroons - Remodel 12 11 \$125,000 910 910 Lobby/Offices - Refurbish 12 11 \$9,000 9110 Cobby/Offices - Refurbish 12 11 \$9,000 9110 Cobby/Offices - Refurbish 15 12 11 \$9,000 9110 Cobby/Offices - Refurbish 15 15 \$15,000 9100 9100 9100 9100 9100 9100 9100	903		12	11	\$150,663	\$208,55
994 Kitchenethes - Refurbish 10 9 \$10,000 1910 206 Lourye - Remodel 12 11 \$132,000 1910 Common Area Bathrooms - Remodel 12 11 \$125,000 1910 Cobernon Area Bathrooms - Remodel 12 11 \$15,000 1910 Cobby Offices - Refurbish 12 11 \$10,000 1910 Cobby Offices - Refurbish 12 11 \$10,000 1910 Cobby Offices - Refurbish 15 15 15 15 15 15 15 15 15 15 15 15 15	903	Office Furnishings/Equip - Replace	12	- 11	\$13,650	\$18.89
1910   Common Area Bathrooms- Remodel   12   11   12   12   100   1910   Gym. *Remodel   10   9   515,000   1910   Lobby/Offices - Refricish   12   11   19,000   1910   Control Finetrions - Regulant   10   9   561,200   1910   Stairwell Interions - Regulant   15   14   543,000   1910   Elevator Cabe Remodel   10   9   970,000	904		10	9	\$10,000	\$13,04
1910 Oys - Remodel   10 9 515,000   1910 Lobby/Offices : Refurbish   12 11 59,000   11110 Corridor Interiors - Repoilet   19 9 561,200   11110 Corridor Interiors - Repoilet   19 9 561,200   1100 Elevator Cabes - Remodel   19 9 370,000   1100 Elevator Cabes - Remodel   19 9 30,000   1100 AC Condensing Units - Replace   20 19 3,500   1100 AC Condensing Units - Replace   20 19	910	240 Lounge - Remodel	12	11	\$125,000	\$173,02
910 LobbyOffices - Refurbish   12   11   93,000	910	Common Area Bathrooms - Remodel	12	11	\$12,000	\$16.61
910 LobbyOffices - Reintrish   12   11   99,000	910		10			\$19,57
1110   Salarvell Interiors - Repaint   15   14   343,000     1502   Elevater Cubes - Remodel   10   9   \$70,000     Sample Coode - Mechanical/Systems   202   Emergency Generator - Overhaul   50   49   \$200,000     303   AC Condensing Units - Replace   20   19   \$9,500     304   Condensing Units - Replace   20   19   \$9,500     305   Next Post Foundation   300   100   100     306   Next Post Foundation   300   100   100     307   Peak Post Foundation   300   100   100     308   Peak Post Foundation   300   100   100     309   Peak Post Foundation   300   100   100     300   Peak Post Foundation   300   100   100     301   302   303   300   300   300     302   303   300   300   300   300     303   300   300   300   300   300     304   305   300   300   300   300     305   300   300   300   300   300     306   300   300   300   300   300     307   300   300   300   300   300     308   300   300   300   300   300     308   300   300   300   300     308   300   300   300   300   300     309   300   300   300   300   300     300   300   300   300   300     300   300   300   300   300     300   300   300   300   300     300   300   300   300   300     300   300   300   300   300     300   300   300   300   300     300   300   300   300     300   300   300   300     300   300   300   300     300   300   300   300     300   300   300   300     300   300   300   300     300   300   300   300     300   300   300   300     300   300   300   300     300	910		12	11		\$12,45
1110   Salarvell Interiors - Repaint   15   14   343,000     1502   Elevater Cubes - Remodel   10   9   \$70,000     Sample Coode - Mechanical/Systems   202   Emergency Generator - Overhaul   50   49   \$200,000     303   AC Condensing Units - Replace   20   19   \$9,500     304   Condensing Units - Replace   20   19   \$9,500     305   Next Post Foundation   300   100   100     306   Next Post Foundation   300   100   100     307   Peak Post Foundation   300   100   100     308   Peak Post Foundation   300   100   100     309   Peak Post Foundation   300   100   100     300   Peak Post Foundation   300   100   100     301   302   303   300   300   300     302   303   300   300   300   300     303   300   300   300   300   300     304   305   300   300   300   300     305   300   300   300   300   300     306   300   300   300   300   300     307   300   300   300   300   300     308   300   300   300   300   300     308   300   300   300   300     308   300   300   300   300   300     309   300   300   300   300   300     300   300   300   300   300     300   300   300   300   300     300   300   300   300   300     300   300   300   300   300     300   300   300   300   300     300   300   300   300   300     300   300   300   300     300   300   300   300     300   300   300   300     300   300   300   300     300   300   300   300     300   300   300   300     300   300   300   300     300   300   300   300     300   300   300   300     300	1110	Corridor Interiors - Repaint	10	9	\$61,200	\$79,85
Sample Condo - Mechanical@ystems   50 49 \$200,000		Stairwell Interiors - Repaint	15		\$43,600	\$65,94
302         Emergency Generator - Overhaul         50         49         \$200,000           303         AC Condensing Units - Replace         20         19         \$9,000           303         Fan Coll Units - Replace         25         24         \$18,000           303         Fan Coll Units - Replace (Common)         20         19         \$84,000           303         Packaged AC Units - Replace         20         19         \$34,000           303         Packaged AC Units - Replace         20         19         \$31,300	1802	Elevator Cabs - Remodel	10	9	\$70,000	\$91,33
303 AC Condensing Units - Replace 20 19 39,500 305 Fan Coll Units - Replace 25 24 511,500 305 Fan Coll Units - Replace (Common) 20 19 384,000 303 Packaged AC Units - Replace 20 19 313,500 313,500 305 Packaged AC Units - Replace 20 19 313,500		Sample Condo - Mechanical/Systems				
303 Fan Coll Units - Replace 25 24 \$18,500 303 Heat Pumps - Replace (Common) 20 19 \$84,000 303 PackAged AC Units - Replace 20 19 \$13,500	302	Emergency Generator - Overhaul	50	49	\$200,000	\$851,24
303 Fan Coil Units - Replace 25 24 518,500 303 Heat Pumps - Replace (Common) 20 19 \$84,000 303 Packaged AC Units - Replace 20 19 513,500	303	AC Condensing Units - Replace	20	19	\$9,500	\$16.65
303 Heat Pumps - Replace (Common) 20 19 \$84,000 303 Packaged AC Units - Replace 20 19 \$13,500	303	Fan Coil Units - Replace	25	24	\$18,500	\$37,60
303 Packaged AC Units - Replace 20 19 \$13,500	303		20	19	\$84,000	\$147,29
	303		20	19	\$13,500	\$23,67
	304		10	9	\$50,000	\$65,23
305 Stairwell Pressure Fans - Replace 20 19 \$16,500						\$28,93
306 Emergency Supply Fans - Replace 20 19 \$16,500						\$28,93
306 Garage Exhaust Fans - Replace 20 19 \$9,000						\$15,78
306 Garage Supply Fans - Replace 20 19 \$19,000						\$33,31


Large, color-coded charts and tables to illustrate long- term implications







# Here's a sample of our Inventory Appendix pages. We devote a half-page summary to every single component included in your Reserve Study.







### **Deliverables**

From the founding of our company, our focus has been on creating a useful, reliable document that can be picked up and understood by any association board member, resident or property manager. Upon completion of the Reserve Study, the Association will receive the following:

- Electronic copy: A digital version of the entire Reserve Study document is delivered by email in PDF form. We also post the completed study to a password-protected location on our website, where association representatives can view and download the entire study, Executive Summary section and funding plan software file.
- Printed copies, upon request: Printed and bound color copies are available upon request. Two copies can be provided at for free. Additional copies will be billed at cost.
- Funding plan software file: We conduct the financial analysis portion of the study using a customized Microsoft Excel® file. Upon completion of the study, we provide this same file to the Association, including fully-functional formulas and input-ready data fields for adding, removing or adjusting component data, such as useful life, remaining useful life and replacement cost estimates. Note: having this file does NOT enable you to create your own Reserve Study and is not intended to be used for the creation of new Reserve Study documents. Rather, we provide this file so that our clients can test "what- if" scenarios, see how their funding plan might change given different interest or inflation rates, and review the "raw" data that went into preparing their study.
- **Complimentary revisions:** we will gladly revise the study at no charge to the client for a period of up to 90 days following delivery of the completed study, in the event that there is a material error or discrepancy identified within the study.
- Video presentation: we will provide a brief video presentation of the Reserve Study to help
  explain the outcomes and provide more background information. The Reserve Study document
  is shown on-screen, and you'll hear our staff describe the key financial details, review the
  component list and explain how we formulate our recommendations in the study. This is ideal
  for sharing at Board meetings, annual association events, etc.
- Additional services: Association Reserves can also provide additional consulting work, attend association meetings, re-visit the property for follow-up inspections, etc. Additional labor charges will be billed at a rate of \$150.00/hour, with a one hour minimum. Travel to and from the property will be billed at the rate of \$50.00/hour. Please contact us directly for more specific information and requests for additional services.





### **References and Testimonials**

You don't get to be in business for 27 years and counting without building a great reputation. Here's what some of our clients have had to say about us recently:

- "As the owner of a fairly large property management company, I have been using Association Reserves since the firm was founded. Excellent staff, timely responses, easy to understand reports, and changing reports has never been problematic! I cannot recommend Association Reserves highly enough."
- "Association Reserves provides incredible service, knowledge and professionalism."
- "Until now, I had yet to see a Reserve Study whose overview so "user" friendly. Any novice may
  pick it up and understand the concepts behind a Reserve Study. Very impressive. To add to that,
  our Project Manager could not be more responsive in answering any of our questions and
  bending over backwards to work with us."
- "I have been in this business since 1998 and not everyone understands how HOAs and Boards work. Association Reserves employees do, which makes my job easier."
- "Our Board could not be more pleased with the report we have received and the manner in which the study was conducted. We highly recommend Association Reserves to prepare your Reserve Study."
- "We have worked with Association Reserves for several years. This is a process which can be very cumbersome to say the least, but Association Reserves has streamlined the process and with their help it has been painless and very successful."
- "Association Reserves far exceeded my expectations in terms of ease of access to our Reserve Study report on the internet, and quality of service."
- "The Association Reserves representatives have been very friendly and professional and have been very responsive to our needs."







# Schedule, Terms & Fees

**Association Name: Silver Point Condominiums** 

**Proposal Number** #28828-0

Level of Service: Full (Level 1) Reserve Study\*

\*If your association has had a prior Reserve Study that you wish to have updated, please contact our office for Reserve Study Update (Level 2 or Level 3) pricing.

Proposal Date: April 13, 2015

### **Description:**

A Full Reserve Study is required when the client has no prior Reserve Study, or wishes to start "from scratch" with a completely new study. This level of service is defined by National Reserve Study Standards as an engagement during which the following five Reserve Study tasks are performed for the first time: Component Inventory, Condition Assessment (based upon on-site visual observations), Life and Valuation Estimates, Fund Status and Funding Plan.

#### Schedule:

Completed Reserve Study will be delivered not more than **8 weeks** from the date we receive your 50% deposit. Alternate pricing for faster delivery is shown below.

### **Payment Terms:**

Payment is required in two installments: 50% of the fee is due upon acceptance of this proposal, with the balance due upon delivery of the draft of the Reserve Study. Refer to the "Deliverables" page included in this proposal for more detail on all items included with our service, including electronic and printed copies of the Reserve Study, a copy of the funding plan software file, and a customized video presentation of the results of the study.

### Fee:

Full (Level 1) Reserve Study: \$5,840 (8-week price)

or \$7,300 (5-week price)

or \$10,950 (2-week price)

### **Proposal acceptance:**

To accept this proposal, please sign and date below and submit this form to our office with your 50% deposit.

We, the undersigned, understand that the Reserve Study being prepared will identify and address the normal deterioration of properly built and installed components with predictable life expectancies. Inspecting for construction defects, performing destructive testing to search for hidden issues (such as plumbing or electrical problems), environmental hazards (asbestos, radon, lead, etc.), or accounting for unpredictable acts of nature are all outside our scope of work. We understand that the above Fee is based on the accuracy of how the Association was described to Association Reserves in our Request for Proposal. If this is not found to be a true representation of our common area maintenance responsibilities, Association Reserves reserves the right to negotiate an adjusted fee for our services. Association Reserves liability in any matter involving this Reserve Study is limited to our Fee for services rendered.

Name:	
	Title:
Signature:	
	Date:



